

General Environmental Incident Summary

Incident: 3556 **Date/Time Notice:** 11/17/2014 **DEM Incident No:**

Responsible Party: RES Americas

Date Incident: 11/17/2014 **Time Incident:** **Duration:**

County: Rolette **Twp:** 163 **Rng:** 69 **Sec:** 3 **Qtr:**

Lat: 48.96624 **Long:** -99.57112 **Method:** Interpolation from map

Location Description: Border Winds Project. Laydown yard. Near culvert staging location.

Submitted By: Shabeeb Abdul Khader

Affiliation: Environmental Supervisor

Address: 10707 52nd Ave

City: Rolla

State: ND

Zip: 58367

Received By:

Contact Person: Shabeeb Abdul Khader
10707 52nd Ave
Rolla , ND 58367

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Equipment Leak

Description of Released Contaminant: Engine Oil

Volume Spilled: 0.01 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

A cup of oil found on the ground under the grader, undergoing routine maintenance.

Risk Evaluation:

None

of Fatalities:

of Injuries:

Affected Medium: 03 - soil

Potential Environmental Impacts:

None. on ground

Action Taken or Planned:

The spoil was collected using a shovel into 5 gallon container. Informed the mechanic to place absorbent pads while refilling oil/fuel.

Wastes Disposal Location: Special waste bin in the laydown yard.

Agencies Involved:

Updates

Date: 11/17/2014 ***Status:*** Reviewed - No Action Required

Author: Espe, Brady

Updated Volume:

Notes:

According to the incident summary, this spill was immediately contained, and cleanup was properly handled. No followup is necessary.